

Overview: Pending Pima County Service Requests

Request Received: 5/4/2023 Requestor: Marilyn Luehrmann Telephone: 630-334-4242 HOA:

Location of Proposed Service: Canoa Hills Trails Park 18 R13E 28

Service Requested: there are some missing roof tiles on the building / structure at Canoa Hills Trails Park, West side of Camino Del Sol by the CHT Parking Lot. Could be a hazard if tiles are not properly affixed.

Pima Co. Contact: Matthew Roberts Status: Exploring what options to address the tiles. LC 8/2/23 GVCCC Request#: 2989

Completion Date: No Change LC 11/7/23 No Change ST 2/6/2024 Just followed up on this last week. Facilities has met with contractors on site and are waiting on quotes for the repair/replacement. Kind Regards, Matt Roberts 3/5/2024 ST No Change 4/2/2024 ST

Request Received: 3/7/2024 Requestor: Jim Wehking Telephone: 619-850-9836 HOA: Canoa Estates

Location of Proposed Service: Intersection of Frontage Road and Camino Encanto 18 R13E 27

Service Requested: Several Large potholes at the intersection of Frontage Road and Camino Encanto

Pima Co. Contact: Richard Enriquez Status: See Click Fix 16176137 and Service Request 24013843 3/7/2024 ST GVCCC Request#: 3062

Completion Date: Waiting on permit from ADOT to do the work. Even though the area in question is ADOT responsibility, PDOT will do the work as soon they get the permit. 4/2/2024 ST Waiting on permit from ADOT to do the work. Even though the area in question is ADOT responsibility, PDOT will do the work as soon they get the permit. 6/3/2024 ST

Overview: Pending Pima County Service Requests

Request Received: 3/27/2024 Requestor: Jim Wehking Telephone: 619-850-9836 HOA:

Location of Proposed Service: W Camino Encanto and West Frontage Road 18 13 27

Service Requested: There a several potholes on W Camino Encanto, just before intersecting W Frontage Road

Pima Co. Contact: Richard Enriquez Status: SeeClickFix 16290691 and Service Request 24014959 3/27/2024 ST GVCCC Request#: 3069

Completion Date: Waiting on permit from ADOT to do the work. Even though the area in question is ADOT responsibility, PDOT will do the work as soon they get the permit. 4/2/2024 ST

Waiting on permit from ADOT to do the work. Even though the area in question is ADOT responsibility, PDOT will do the work as soon they get the permit. 6/3/2024 ST

Request Received: 5/29/2024 Requestor: Brad Freiheit Telephone: 414-617-7009 HOA: Viewpoint Homeowners Assn

Location of Proposed Service: Wash between 991 W Rio Magdalena and 991 W Rio Hondo 18 R13E 3

Service Requested: Arroyo located between 991 W Rio Magdalena and 999 W Rio Hondo, on West and East side of N Via Alamos. Please evaluate and clean brush and trees that are now overgrown.

Pima Co. Contact: Luke Heinzelman Status: Thanks Sue, we will inspect and keep you in the loop. D/ebbie, please log this in for inspection. Screen GVCCC Request#: 3081

Completion Date: shot below of area in questions. Poly is 19374. Per Luke 5/29/24 STHi all,

This concern has been logged in as DC24-261 Thank you Debbie Grijalva Regional Flood Control District 5/31/2024 ST

Overview: Pending Pima County Service Requests

Request Received:	6/3/2024	Requestor:	Marilyn Luehrmann	Telephone:	630-334-4242	HOA:	Desert Hills III West	
Location of Proposed Service:	Bottom of hill at S Camino Mercado and S Retorna De Anza					18	R13E	28
Service Requested:	At the bottom of the hill, on the curve, is a double stacked curb, which has split apart. One of the curbs is pushed out into the road. There are no sidewalks there, so if walking on the road it causes a tripping hazard. PHOTO ATTACHED							
Pima Co. Contact:	Richard Enriquez	Status:	SCF# 16757754 SR# 24018686 6/4/2024 ST			GVCCC Request#:	3082	
Completion Date:								

Request Received:	6/4/2024	Requestor:	Delvin Prophet	Telephone:	480.440.3860	HOA:	Fairways 2	
Location of Proposed Service:	The Alley behind 417 East Las Milpas					18	R13E	11
Service Requested:	The Alley behind my home is torn up and littered with junk ie; concrete, bricks, Rock, and glass among other things. The original asphalt is getting pushed up from the monsoon rain and its creating potholes and a stream that carries mud onto the sidewalk and into the street. A number of our elderly have slipped in the mud when trying to walk on the sidewalk when this happens. We need about 60 feet of the alley cleaned up where it exits onto the sidewalk and the street. Also, some rip-rap should be put down put down (River Rock or new asphalt) to prevent the mudslide onto the sidewalk and then the street							
Pima Co. Contact:	Richard Enriquez	Status:	Good morning Sue and thank you for reaching out. I have put in Del's request for the alleyway for stabilization which is SCF 16764604. However, cleaning and maintaining the alleyway is the responsibility of the residence. I have attached our alleyway policy to this email. Thank you! PC 6/4/2024 ST			GVCCC Request#:	3083	
Completion Date:								